

S. J. McKee Archives



Signature wall

<http://archives.brandonu.ca/en/permalink/descriptions8119>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.47

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

History /

Biographical:

The signature wall is a name created by the Archives and given to a piece of wall formerly located in either Clark Hall or the Brandon College Building that was covered in former students signatures. The signatures were discovered at the time of renovations to the building.

Scope and Content:

Photograph shows President Dennis Anderson examining the signature wall.

Images





Outer wall construction

<http://archives.brandonu.ca/en/permalink/descriptions8132>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.61

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph was taken from the basement looking up and shows support beams, two outer walls covered in vapor barrier plastic, some windows and the missing roof.

Images





Outer wall construction

<http://archives.brandonu.ca/en/permalink/descriptions8133>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.62

GMD: graphic

Date Range: c. 1996


Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph was taken from the basement looking up and shows support beams, an outer wall covered in vapor barrier plastic, some windows and the missing roof. The windows may be part of one of the stairwells.

Images





Interior shot of exterior wall

<http://archives.brandonu.ca/en/permalink/descriptions8138>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.67

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph was taken from inside the building looking up to show the exposed exterior wall.

Images





Exterior wall and new construction

<http://archives.brandonu.ca/en/permalink/descriptions8140>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.69

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph was taken outside to show where new support beams met the existing structure.

Images





North wall of Clark Hall under construction

<http://archives.brandonu.ca/en/permalink/descriptions8196>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.105

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph is looking south and shows stone portion of the north wall of Clark Hall under construction.

Images





Construction materials along the north wall of Clark Hall

<http://archives.brandonu.ca/en/permalink/descriptions8197>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.106

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph is looking east southeast and shows construction materials laying outside along the north wall of Clark Hall.

Images





Prior to interior walls

<http://archives.brandonu.ca/en/permalink/descriptions8144>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.73

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph shows the concrete floor and support beams, prior to interior wall construction, for one of the floors in Clark Hall and the Brandon College Building.

Images





Aerial view: Brandon University campus

<http://archives.brandonu.ca/en/permalink/descriptions2576>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 9

Item Number: BUPC 9.36

GMD: graphic

Date Range: September 21, 1999

Physical Description: 11" x 14" (colour)

History /

Biographical:

The photograph was taken for the Centennial of Brandon College/University.

Scope and Content:

Aerial photograph taken looking southwest from approximately the northeast corner of Princess Avenue and 17th Street. The entire campus, as well as a number of residential streets are visible.

Notes: Negative is located with the photograph

Subject Access: campus buildings
aerial photographs
aerial photography
aerial views
cityscapes

Storage Range: Oversized drawer 4

Images





Site Services Building

<http://archives.brandonu.ca/en/permalink/descriptions710>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.12

Item Number: BUPC 2.12.5

GMD: graphic

Date Range: [197-]

Physical Description: 8" x 10" (b/w)

History /

Biographical:

The Site Services building was built in 1971.

Scope and Content:

Photograph is looking northwest and shows the exterior of the Site Services Building located on at 20th Street and Louise Avenue.

Images





George Cibinel at the construction site

<http://archives.brandonu.ca/en/permalink/descriptions8121>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.50

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph shows George Cibinel, Chief Architect of the Brandon College Building and Clark Hall renovations.

Images





Site services building construction

<http://archives.brandonu.ca/en/permalink/descriptions14358>

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item

Series Number: 2.12

Item Number: BUPC 2.12.27

GMD: graphic

Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History /

Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Also visible are McMaster Hall, Flora Cowan Women's Residence and the John R. Brodie Science Centre. Photograph is looking east/northeast from approximately 21st Street.

Notes: Donkersloot recorded the date and time each photograph was taken on the back of the photos.

Images





Site services building construction

<http://archives.brandonu.ca/en/permalink/descriptions14359>

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item

Series Number: 2.12

Item Number: BUPC 2.12.28

GMD: graphic

Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History /

Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services Building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Also visible are McMaster Hall and part of Darrach Hall. Photograph is looking northeast.

Notes: Donkersloot recorded the date and time each photograph was taken on the back of the photos.

Images





Site services building construction

<http://archives.brandonu.ca/en/permalink/descriptions14360>

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item

Series Number: 2.12

Item Number: BUPC 2.12.29

GMD: graphic

Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History /

Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services Building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Photograph is looking northwest.

Notes: Donkersloot recorded the date and time each photograph was taken on the back of the photos.

Images





Members of the Brandon University Foundation tour the construction site

<http://archives.brandonu.ca/en/permalink/descriptions8120>

Part Of: Brandon University Photograph Collection

Description Level: Item

Series Number: 2.2

Item Number: 2.2.48

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph shows members of the Brandon University Foundation during a tour of the construction site. Members include: Scott Stewart, Doug Adams, Sheri Decter-Hirst.

Images

