

S. J. McKee Archives



Site services building construction

http://archives.brandonu.ca/en/permalink/descriptions14358

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item
Series Number: 2.12

Item Number: BUPC 2.12.27

GMD: graphic
Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History / Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Also visible are McMaster Hall, Flora Cowan Women's Residence and the John R. Brodie Science Centre. Photograph is looking east/northeast from approximately 21st Street.

Notes: Donkersloot recorded the date and time each photograph was taken on

the back of the photos.

Images



S. J. McKee Archives p. 1



Site services building construction

http://archives.brandonu.ca/en/permalink/descriptions14359

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item
Series Number: 2.12

Item Number: BUPC 2.12.28

GMD: graphic

Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History / Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services Building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Also visible are McMaster Hall and part of Darrach Hall. Photograph is looking northeast.

Notes: Donkersloot recorded the date and time each photograph was taken on

the back of the photos.

Images



S. J. McKee Archives p. 2



Site services building construction

http://archives.brandonu.ca/en/permalink/descriptions14360

Part Of: Brandon University Photograph Collection

Creator: Photographer: Tom Donkersloot

Description Level: Item
Series Number: 2.12

Item Number: BUPC 2.12.29

GMD: graphic

Date Range: May 4, 1971

Physical Description: 4.25" x 3.25" (b/w)

History / Biographical:

Donkersloot began working at Brandon University in 1970/1971 as the Clerk of Works. From 1973 until his retirement, he was the Director of Physical Plant.

The Site Services Building was built in 1971.

Custodial History:

Photograph was taken by Tom Donkersloot during construction and stored in albums in the Physical Plant H-Hut until they were transferred to the McKee Archives by Doug Duncalf in May 2008.

Scope and Content:

Photograph shows construction of Brandon University's Site Services Building located on Louise Avenue at the corner of 20th Street. Photograph is looking northwest.

Notes: Donkersloot recorded the date and time each photograph was taken on

the back of the photos.

Images



S. J. McKee Archives p. 3