

S. J. McKee Archives



Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8007>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.73

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is southeast from the roof of Clark Hall. Photograph shows some of the scaffolding and materials, as well as the construction trailer (Bird Construction) located on the driveway during the restoration of Clark Hall and the Brandon College Building.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8008>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.74

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is southwest from Clark Hall. Photograph shows the construction of the foundation of the extension of Clark Hall and various construction materials located in the courtyard.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8013>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.79

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:


View is north from the courtyard looking underneath the skywalk. Photograph shows the grading of the road between the Clark Hall extension and the A.E. McKenzie Building.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8015>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.81

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is west from the roof of the Brandon College Building. Photograph was taken through wire fencing and shows roof beams during construction on the roof of the Brandon College Building during winter. Part of the George T. Richardson Centre and the second steam plant are visible in the background, as well as a few houses.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8024>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.90

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Image is looking north along the driveway in front of Clark Hall and the Brandon College Building, and shows building materials, equipment and debris. The photograph was taken during the renovations of the Brandon College Building and Clark Hall.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8025>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.91

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is west from the sidewalk between the Brandon College Building and the Citizens' Science Building. Photograph shows an H-Hut, two trailers and general construction mayhem.

Subject Access: campus photographs

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8000>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.66

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is southeast from the roof of the A.E. McKenzie Building. Photograph shows the construction of the extension of Clark Hall and the skywalk.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8001>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.67

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is north probably from the roof of McMaster Hall. Photograph shows the construction of the extension of Clark Hall and the skywalk.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8002>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.68

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is north probably from the roof of McMaster Hall. Photograph shows the construction of the new roof on Clark Hall and the Brandon College Building.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8003>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: 2.1.69

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is southwest from Clark Hall. Photograph shows the construction of the extension of Clark Hall.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8010>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.76

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is southeast from Clark Hall. Photograph shows a large crane, building materials and machines and the construction trailer (Bird Construction) on the driveway during the restoration of Clark Hall and the Brandon College Building. Portions of the front lawn, the John R. Brodie Science Centre and the Knowles Douglas Students' Union Centre are also visible. In the distance is Knox United Church.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8019>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.85

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is southwest from the roof of Clark Hall. Photograph shows the construction of the foundation and exterior walls of the Clark Hall extension. George T. Richardson Centre and construction materials in the background.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8022>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.88

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is north northwest from the roof of the John R. Brodie Science Centre. Photograph shows the Knowles Douglas Students' Union Building, and the Citizens' Science Building, the Brandon College Building and Clark Hall under restoration, as well as parts of the driveway and front lawn, including the flag pole.

Subject Access: campus photographs

campus buildings

campus construction

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8011>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.77

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is northwest from Clark Hall. Photograph shows construction materials in the area between Clark Hall and the A.E. McKenzie Building during winter. The Western Manitoba Centennial Auditorium is visible in the upper right hand corner.

Subject Access: campus photographs
campus buildings
campus construction
winter

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8012>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.78

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is south southeast from the skywalk. Photograph shows the courtyard in winter full of vehicles, machines and building materials. Also visible are the Development and Physical Plant H-Huts, the Citizens' Science Building, the John R. Brodie Science Centre and McMaster Hall.

Subject Access: campus photographs
campus buildings
campus construction
winter

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8014>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.80

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is northwest from the roof of the Brandon College Building. Photograph was taken through wire fencing and shows construction on the roof of the Brandon College Building during winter. The original Clark Hall entrance to the roof is clearly visible. Portions of the A.E. McKenzie Building, Clark Hall and the Western Manitoba Centennial Auditorium are visible in the background.

Subject Access: campus photographs

campus buildings

campus construction

winter

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8021>

Part Of: Brandon University Photograph collection

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.87

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

Photograph was taken from the skywalk and shows students leaving the George T. Richardson Centre during winter. The courtyard contains construction materials. The Physical Plant H-Hut and McMaster Hall are partially visible in the background.

Subject Access: campus photographs
campus buildings
campus construction
winter

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8016>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.82

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is northeast from the Brandon College Building. Photograph shows the inside of the Brandon College Building after it had been gutted and then partially rebuilt. The exterior facade of the west side of the building can be clearly seen in this photograph. A number of houses on the east side of 200 block of 18th Street are also visible, as is the stone fence on Princess Avenue and the flag pole on the front lawn.

Subject Access: campus photographs

campus construction

Brandon streets

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8005>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.71

GMD: graphic

Date Range: c. 1996

Physical Description: 4" x 6" (colour)

Scope and Content:

View is northeast probably from the roof of McMaster Hall. Photograph shows the construction of the new roof on Clark Hall and the Brandon College Building. A portion of the east side of the 000 and 100 blocks of 18th Street, as well as the corner of 18th Street and Rosser Avenue are visible in the upper left hand corner. This includes the "Downtown Brandon" sign.

Subject Access: campus photographs

campus buildings

campus construction

Brandon streets

Images





Brandon University campus construction

<http://archives.brandonu.ca/en/permalink/descriptions8006>

Part Of: Brandon University Photograph collection

Creator: Photographer: Sandy Black

Description Level: Item

Series Number: 2.1

Item Number: BUPC 2.1.72

GMD: graphic

Date Range: c. 1996

Physical Description: 6" x 4" (colour)

Scope and Content:

View is north northeast probably from the roof of McMaster Hall. Photograph shows the construction of the new roof on Clark Hall and the Brandon College Building, as well as the construction of the extension to Clark Hall and the skywalk. Portions of the city as far north as the Assiniboine River are also visible.

Subject Access: campus photographs

campus buildings

campus construction

Brandon streets

Images

